Ref No. BMM/ENV/2020-21/01



Date: 15.05.2020

To. **Environmental Officer** KSPCB Regional Office, Sy No.597P, Ward No.15, 4th Main, Near Dr. Vishnuvardhana Park, Kuvempunagara, Ballari-583104

> Sub: Submission of Annual Returns in Form-IV as per BMW Rules-2016 Ref.No: Authorization No.: 324\KSPCB/Ro (BLY)/BMW/2017-18/1903 Date: 23.01.2018

Dear Sir.

With reference to the above subject, we here by submit the annual returns in form-IV for generation, storage and disposal of Bio medical waste as per Bio-Medical Waste Management Rules- 2016 for the period of January-2019 to December-2019, in respect of Occupational health center in BMM ISPAT LTD., Danapura, Hosapete Taluk, Ballari District...

Kindly acknowledge the receipt of the same.

Yours Faithfully

For BMM Ispat Ltd.,

Mr. Narasimha Murthy Karnam

Occupier

Enclosed: Form-IV (annual returns for BMW)

BMM Ispat Ltd. Registered Office & Works: 114, Danapur Village, Hosapete - 583 222 Ballari District, Karnataka, India. t. +9199723 09413/417 f. +91 83 9426 4010

BMM Ispat Ltd. Corporate Office: 101, 1st Floor, Pride Elite, 10, Museum Road, Bengaluru-560 001 Karnataka, India. t. +91 80 41495660/1/3 f. +91 80 4149 5664

Cin: U13100KA2002PLC030365 Email: bmmispat@bmm.in Website: www.bmm.in





## Form - IV (See rule 13) ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30<sup>th</sup> June every year for the period from January to December of the preceding year, by the occupier of health care facility (HCF) or common bio-medical waste treatment facility (CBWTF)]

Sl.	Particulars and the second sec	:	Details asits of laborates	
No	In the Committee			
psin/	Particulars of the Occupier  (i) Name of the authorized person (occupier	:	Mr. Narasimha Murthy Karnam	
	or operator of facility)		Occupier	
	(ii) Name of HCF or CBMWTF	;	Occupational Health Center M/s. BMM Ispat Ltd, Danapura	
	(iii) Address for Correspondence	:	M/s. BMM Ispat Ltd, #114, Danapura Village, Mariyammanahalli Hobli, Hosapete taluk, Ballari District	
	(iv) Address of Facility	å	M/s. BMM Ispat Ltd, #114, Danapura Village, Mariyammanahalli Hobli, Hosapete taluk, Ballari District	
	(v)Tel. No, Fax. No		Tele:+91 8394-264001 Mob:+91 9972309417 Fax: +91 80 3072 3604	
	(vi) E-mail ID	:	santoshmd@bmm.in, medicalofficer@bmm.in	
	(vii) URL of Website	:	www.bmm.in	
	(viii) GPS coordinates of HCF or CBMWTF		N:15°10'13.79" E:76°22'34.19"	
	(ix) Ownership of HCF or CBMWTF	:	M/s. BMM Ispat Ltd, Danapura.	
	(x). Status of authorization under the Bio- Medical Waste (Management and Handling) Rules		Authorization No.: 324\KSPCB/Ro(BLY)/BMW/201 18/1903 Date:23.01.2018	
	(xi). Status of Consents under Water Act and Air Act	:	CFO Valid up to: 30.06.2022	
2.	Type of Health Care Facility	1	No.of Beds: Nil	
	(i) Bedded Hospital	:	NA	
	(ii) Non-bedded hospital(Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other)	*	Yes (Occupational Health Center)	
	(iii) License number and its date of expiry	1	NA	
	Details of CBMWTF	:	NA	
5 lin	(i)Number healthcare facilities covered by CBMWTF	1:	NATION (Induced) Induced Over the Art Innounced For the becomes our series as	
	(ii) No of beds covered by CBMWTF	1	NA holigon for 3001 redition to said part	
	(iii) Installed treatment and disposal capacity of CBMWTF:	:	NA straye labeliació	
	(iv) Quantity of biomedical waste treated or disposed by CBMWTF	gru		
4.	Quantity of waste generated or disposed in Kg	:	Yellow Category: 15.55 Kg/Annum	
	per annum (on monthly average basis)		Red Category :17.06 Kg/Annum	
	228	Mil	White: 15.55 Kg/Annum	
		:	Blue Category :13.96 Kg/Annum	

Details of the Storage, treatment, transportation, pro  (i) Details of the on-site storage facility	1	Stored in 4 bins	-		
The state of the s	44	Capacity: 10 litre			
AL REPORT		1			
radi most bestog an sylvas vers covaring. The appropri on teality care masses (HCT) or continuation of the		Provision of on-Site Storage: Storage & Segregation Different Category colored bins like Yellow Bins, Ro Bins, Blue Bins, and White Bins.			
(ii) Details of the treatment or disposal facilities		Type of Treatment	No. of Units	Capacity in Kg/Day	Quantity treated or disposed in kg/Annum
	7	Incinerators	Nil	Nil	Nil
	I	Plasma Pyrolysis	Nil	Nil	Nil
	-	Autoclaves	Nil	Nil	Nil
Occupational Health Corner		Microwave	Nil	Nil	Nil
Mrs. BMM Ispan Ltd. Danagram	-	Hydroclave	Nil	Nil	Nil
Mrs. BMM Ispar Led		Shredder	Nil	Nil	Nil
nt 14, Donapum is diago. Many amnanabalis frebli		Needle tip cutter or destroyer	Nil	Nil	Nil
		Sharps	Nil	Nil	Nil
Mrs. BMM ispat i ti		encapsulation or	Nil	Nil Combo	Nil
#114, Danapura Village		concrete pit			
Manyan manahalli Robin		Deep burial pits	Nil	Nil	Nil
		Chemical	Nil	Nil	Nil
		Disinfection	Nil	Nil	Nil
	1	Any other treatment			
		equipment			
		1)BP Apparatus	04No,s	Nil	Nil
	1	2)SPO <sub>2</sub>	02No,S	Nil	Nil
		3)Suction Machine	01	Nil	Nil
		4)Weighing Machine	01	Nil	Nil
		5)Hematology	00	NET.	277
		Analyzer	00 1 11 1	Nil	Nil
Auf Johnson on No. 124 W.SECIERO(BL VEBM	-Ciri	6)Bio-Chemistry	2000000	Status of	Nil
18 Fruit Date 23(6) 2018	200	Analyzer	00	Nil	Nil
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum. Red Category (like plastic, glass etc.)	I TAK	pA aprivi telica	ilial et		(18) I 1 & TET
(iv) No of vehicles used for collection and transportation of biomedical waste	:	Vehicle of CBMW		Bedded Hos	(1) yet
(v) Details of incineration ash and ETP sludge generated and disposed during the treatment of wastes in Kg per annum	:	Quantity generated: Where disposed: Incineration: Ash: NA ETP Sludge:			
(vi) Name of the Common Bio- Medical Waste Treatment Facility Operator through which wastes are disposed of		M/S Suryakanth Entaluk & District	vironmenta	al Technologie	es., Ballari
(vii) List of member HCF not handed over bio- medical waste.	: /:	pages separation has		u boilen it a	Tigger
Do you have bio-medical waste management committee? If yes, attach minutes of the meetings held during the reporting period		l wase mened or		To gates of	
Details trainings conducted on BMW	:	The same of the same		TRE I STELL THE	
(i) Number of trainings conducted on BMW Management.		13,850° U <u>E</u> 610		no i mums	DC'
(ii) Number of personnel trained	:				(EPAT
(iii) Number of personnel trained at the time of induction	:				(3)

7	(iv) Number of personnel not undergone any training so far		
	(v) Whether standard manual for training is available?	:	***
	(vi)Any other information)		****
8.	Details of the accident occurred during the year	:	
	(i) Number of Accidents occurred	1	NILL
	(ii) Number of the persons affected	:	NILL
	(iii) Remedial Action taken (Please attach details if any)	:	NILL
	(iv) Any Fatality occurred, details.	:	
9.	Are you meeting the standards of air Pollution from the incinerator? How many times in last year could not met the standards?	:	***
	Details of Continuous online emission monitoring systems installed		
10.	Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year?	:	
11.	Is the disinfection method or sterilization meeting the log 4 standards? How many times you have not met the standards in a year?		
12.	Any other relevant information (Air Pollution Control Devices attached with the Incinerator)		

Certified that the above report is for the period from 01.01.2019 to 31.12.2019.

Date: 15.05.2020

Place: Danapura

Mr. Narasimha Murthy Karnam Occupier

(Name and Signature of the Head of the Institution)

